


OPERATING INSTRUCTIONS FOR POCKET DIGITAL MULTIMETER WAT115A



SAFETY INFORMATION

The following safety information must be observed to ensure maximum personal safety during the operation of this meter.

Do not use if meter or test leads look damaged, or if you suspect that the meter is not operating properly.

Never ground yourself when taking electrical measurements. Do not touch exposed metal pipes, outlets, fixtures, etc., which might be at ground potential. Keep your body isolated from ground by using dry clothing, rubber shoes, rubber mats, or any approved insulating material.

Turn off power to the circuit before cutting, desoldering, or breaking the circuit. Small amounts of current can be dangerous.

Use caution when working above 60V DC or 30V AC rms. Such voltages pose a shock hazard.

When using the probes, keep fingers behind the finger guards.

Measuring voltage which exceeds the limits of the multimeter may cause damage to the meter and expose the operator to a shock hazard. Always be aware of the meter voltage limits as stated on the front of the meter.

SPECIFICATIONS

Display: 3 1/4 digit liquid crystal display (LCD) with a maximum reading of 3999

Polarity: Automatic, positive implied, (-) negative polarity indication.

Overrange: "OL" mark indication.

Low Battery Indication: The " " is displayed when the battery voltage drops below the operating level.

Measurement Rate: 2 times per second, nominal.

Auto Power Off: approx. 10 minutes.

Operating Environment: 0°C to +40°C at <70% R.H.

Storage Temperature: -20°C to +60°C at < 80% R.H. with battery removed from meter.

Temperature Co-efficient: 0.1 x (specified accuracy) per °C. (0°C to 18°C, 28°C to 40°C).

Power: Two 1.5 button-type batteries (IEC# LR-44, NEDA # 1166A).

Battery Life: 70 hours continuous operation.

Dimensions: 125mm (H) x 60mm (W) x 24mm (D).

Weight: Approx 110g including batteries and case.

(Accuracy at 23°C ± 5°C, <75% R.H.)

	Range	Resolution	Accuracy	Input Impedance	Overload Protection
DCV	4V	1mV	± 2.0% rdg + 2dgs	10MΩ	600V DC or AC rms
	40V	10mV			
	400V	100mV		9.1MΩ	
	600V	1V			
ACV (50-60Hz)	4V	1mV	± 4.0% rdg + 5 dgs	10MΩ	
	40V	10mV			
	400V	100mV		9.1MΩ	
	600V	1V			
OHM	400Ω	100mΩ	± 2.0% rdg + 5 dgs	Open circuit Volts -1.2 Vdc	450V DC or AC rms
	4kΩ	1Ω			
	40kΩ	10Ω	± 2.0% rdg + 4 dgs		
	400kΩ	100Ω			
	4MΩ	1kΩ	± 3.0% rdg + 4 dgs	Open circuit Volts-0.45 Vdc	
	40MΩ	10kΩ	± 5.0% rdg + 5 dgs		
Diode Test Continuity	2V	10mV	± 3.0% rdg + 3 dgs	Test current 1.2mA	450V DC or AC rms
	400Ω	1Ω	Audible indication: < 25Ω	Response Time: 500ms	450V DC or AC rms
NON-CONTACT VOLTAGE INDICATOR: Detects voltage from 70V to 600V AC 50Hz -60Hz					

OPERATION

Before using meter please read the Safety Information section. Always examine the meter for damage, contamination (excessive dirt, grease, etc.) and defects. Examine the test leads for cracked or frayed insulation. If any abnormal conditions exist do not attempt to use.

AUTORANGING:

The meter defaults to autorange when you turn it on. In autorange, the meter selects the range automatically.

DATA HOLD FEATURE:

Press (HOLD) button to toggle in and out of the Data Hold mode. In data hold mode, “HOLD” and the last reading are displayed. Press (HOLD) button again to release. The hold and current reading are once again displayed.

MODE SWITCH (DC/AC):

When the function switch is set to (Ω / \bullet) / \rightarrow () position press button to toggle between DC and AC in the voltage measurements. Press this switch to toggle between the continuity/diode and ohms modes.

MEASURING VOLTAGE:

1. Set the Function Switch to “VOLT” position.
2. To toggle between “DC” & “AC”, press Mode switch. The “DC to “AC” mark is displayed.
3. Touch the probes to the test points, the range will change automatically to the level that will display the best input voltage resolution.
4. The value indicated in the display window is the measured value of voltage.

MEASURING RESISTANCE & TESTING CONTINUITY:

1. Set the Function Switch to (Ω / \bullet) / \rightarrow () position.
2. Turn off power to the circuit under test. External voltage across the components causes invalid readings.
3. To toggle between the ohms/continuity/diode modes, press Mode Switch.
4. Touch the probes to the test points. In ohms, the value indicated in the display is the measured value of resistance. In continuity testing, the beeper sounds continuously, if the resistance is less than approximately 25 Ω

TESTING DIODES

1. Set the Function switch to (Ω / \bullet) / \rightarrow () position.
2. Turn off power to the circuit. External voltage across the components causes invalid readings.
3. To toggle between the ohms/continuity/diode modes press Mode Switch.
4. Touch probes to the diode. A forward-voltage drop is about 0.6V (typical for a silicon diode).
5. Reverse probes. If the diode is good, “OL” is displayed. If the diode is shorted, a value near 0mV will be displayed.
6. If the diode is open, “OL” is displayed in both directions.
7. Audible Induction: Less than 0.25V.

NON-CONTACT VOLTAGE INDICATOR:

1. Store the test leads on back of meter before taking NCV measurement.
2. Set switch to OFF/NCV position. Press and hold the NCV button and aim sensor to the object to be detected. When a voltage is detected, the NCV LED and beeper will stay on.

NOTE: If battery is low, beeping sound may be less audible and may not work. Replace batteries in this instance.

AUTO POWER OFF:

1. Power turns off automatically after 10 minutes.
2. Press (HOLD) button to restart and display last measurement reading.



SAFETY: Conforms to IEC1010-1 (EN61010-1), Rev-2; CATII 600V, CATIII 300V; Class 2, Pollution degree II.

EMC: Conforms to EN61326.

The symbols used for this instrument are:



Caution, refer to accompanying documents.



Equipment protected throughout by Double insulation (Class II)



Alternating current.




Direct current



Ground

BATTERY REPLACEMENT:

Power is supplied by two 1.5V button type batteries (NEDA 1166A, IEC LR-44). “” Symbol appears when battery needs replacing.

WARNING

Before attempting to replace the batteries disconnect the Test Leads from any energised circuit first.

1. Disconnect the test leads from any energised circuit.
2. Set the Function Switch to OFF.
3. Remove battery cover screw.
4. Slide off battery cover and change batteries.
5. Replace battery cover and screw back.

BATTERY REPLACEMENT DIAGRAM

